ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0695, W0602, W0683, W0693, W0689, W0606	NA	Ramachandra area
Segment No.	**Total Length (m)**	
11/C-W0695/S032653	213.09	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	60.62	77.550284	13.061699	77.550419	13.062231	muniramaiah block	cross road
2	76.48	77.549659	13.062124	77.550349	13.061983	muniramaiah block 1st cross	cross road
3	75.99	77.549594	13.061838	77.550279	13.061697	muniramaiah block 2nd cross	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains and construction of culverts at Ramachandrapura and surrounding area in ward no. 11 Kuvempunagara in Vidyaranyapura sub divisio	2500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC drain	011-17-000028
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/209/2016-17	08/03/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
31/07/2017	31/07/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.Shankar reddy		0.00
Phone No.	**E-Mail ID**	

1546

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0695, W0602, W0683, W0693,

Inspection Details

Number of Trees

Any Other Information

Name

Gurusiddappa c gokale

Date of Inspection

20/07/2017

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Segment End		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0695, W0602, W0683, W0693,

rks

ation	Approver Name	Date	Target Date	Remark
	Parameshwaraiah	20/07/2017	19/08/2017	Approved
	K.M.Vasu	20/07/2017	19/08/2017	complete
EE	H.T.Mohan das	20/07/2017	19/08/2017	complete
AEE	Shivakumar m gowdar	20/07/2017	19/08/2017	Verify
AE	Gurusiddappa C Gokhale	20/07/2017	19/08/2017	Mobile verification done
AE	Gurusiddappa C Gokhale	20/07/2017	19/08/2017	Forward

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0695, W0602, W0683, W0693,